

Fig 1a - f

Fig 1f

Fig 1e

Fig 1d

Fig 1c

Fig 1b

Fig 1a




Fig. 2




Fig 3




Fig 4





Fig 5



204210-EB92E660




FIGURE 7

BOLT FULLY INSTALLED
THE RIG RETRACTS AND THE BOLT
HAS BEEN FASTENED IN THE ROOF.